Address: #22, 1st Floor, Sirsa Club, Janta Bhawan Road, Sirsa

ISHAN NARANG CIVIL ENGINEER, A.I.O.V. GOVT. APPROVED VALUER (A 26871)

Email: narangvaluer@gmail.com GST No: 06AGSPN4042K220 Mob: 9540655000, 9215620210

REF.NO. 012024-02

Date: 01-01-2024

CERTIFICATE

Certified that the above said school i.e. Vivekanand Bal Mandir Senior Secondary School, Rania Road, Sirsa was inspected by me on Monday i.e. 01-01- 2024. Block A to E occupied by the school authority are as per building bylaws in accordance with rule of state and incorporate the provision of building safety as specified in National Building Code 2005, 2016 and amended thereafter, has been verified by the u/signed in the presence of school staff manager. On the basis of facts explained above, the building has been found to be fit to conduct classes for the next two years i.e. for 01.01.2024 to 31.12.2025.

PLACE: SIRSA DATE: 01-01-2024

Manager Vivekanand Bal Mandir Sr. Sec. School, Sirsa

4- 6-2-2024 koal

Vivekanand(B.M) Sr. Sec. School SIRSA(Harvana)

Address: #22, 1st Floor, Sirsa Club, Janta Bhawan Road, Sirsa

ISHAN NARANG CIVIL ENGINEER, A.I.O.V. GOVT. APPROVED VALUER (A 26871) Email: narangvaluer@gmail.com GST No.: 06AGSPN4042K2Z0 Mob: 9540655000, 9215620210

REF.NO. 012024-02

Date; 01-01-2024

TO WHOM IT MAY RELATE

Subject - FITNESS-CERTIFICATE (FOR SCHOOL BUILDING)

1. Name Of The Inspecting Engineer:

2. Name Of The School:

3. Location With The Name:

ER. ISHAN NARANG CIVIL ENGINEER, A LO.V.

Vivekanand Bal Mandir Senior Secondary School, Sirsa

Situated At Rania Road, Vill, Khaja Khera Within MC Limit, Sirsa -125055, Tehsil & Distt, Sirsa

4. Classification of Building Specification:

Building is as per A-Class

5. Year Of Construction Of Different Buildings -

Main Building Block Marked As "A"

Year of Construction:	2007-08
Permanent Size:	1) GF = 22333.80 SQ FT OR 2074.81 SQ MTR
	2) FF = 21613.86 SQ FT OR 2007.92 SQ MTR

Girls Block Marked As "B"

2008-09 v 1) GF = 12836.62 SQ FT OR 1192.52 SQ MTR

Primary Block Marked As "C"

Year of Construction: Permanent Size:

2011-12 1) GF = 3004 SQ FT OR 279 SQ MTR 2) FF = 3004 SQ FT OR 279 SQ MTR



6-02-4024 rinoloal

Vivekanand(B.M) St, Sec. School SIRSAT arvana)

Managor Vivekanand Bal Mandir Sr. Sec. School, Sirsa

Address: #22, 1st Floor, Sirsa Club, Janta Bhawan Road, Sirsa

ISHAN NARANG CIVIL ENGINEER, A.1.O.V. GOVT. APPROVED VALUER (A 26871) Email: narangvaluer@gmail.com GST No.: 06AGSPN4042K2Z0 Mob: 9540655000, 9215620210

REF.NO. 012024-02

Date: 01-01-2024

Multi-Purpose Hall Marked As "D"

Year of Construction:	2013-14
Permanent Size:	1) GF = 7000 SQ FT OR 650.32 SQ MTR.

Auditorium Marked As "E"

Year of Construction:	2015-16
Permanent Size:	 GF = 4700 SQ FT OR 436.64 SQ MTR.

Temporary Shed

Year of Construction: Permanent Size: 2013-14 1) GF = 1200 SQ FT OR 111.48 SQ MTR.

6. Period for which is certificate is issued:

Two Years (01.01.2024 to 31.12.2025)

No defects have been notices. It is new

building with A class classification.

Open foundation with spread footing

Observation/comments by inspecting engineer

7. Nature of defects, if any:

a) Foundation & Basement

b) Superstructure

c) Doors and windows

plaster. 1st class brick masonry in cement

along with RCC columns outside cement

sand mortar with inside outside cement Plaster.

Hard wood like champ, Assam Devdar aas been used in doors and windows Painted with ready mixed paints



2-2021

Vivekanand(B.M) Sr. Sec. School SIRSA(Harv.na)

2

Manager Vivekanand Bal Mandlr Sr. Sec. School, Sirsa

Address: #22, 1st Floor, Sirsa Club, Janta Bhawan Road, Sirsa

ISHAN NARANG CIVIL ENGINEER, A.I.O.V. GOVT, APPROVED VALUER (A 26871) Email: narangvaluer@gmail.com GST No. 06AGSPN4042K2Z0 Mob. 9540655000, 9215620210

REF.NO. 012024-02

- d) Wood work wrought and put
- e) Roof
- f) Flooring
- g) Miscellaneous (Craks, etc.) noticed
- Any Major Defects noticed which will Render the building unsafe in any manner.
- Whether maintenance works have been done properly;
- Whether the structure is sound or not for conducting classes:
- The stability of the Structure should be examined also with reference to location, altitude, intensity of wind exposure to flood, etc.
- Any additional observation if deemed necessary for the certificate may be furnished separately with the Certificate:

Vivekandrid Bal Mandir

Sr. Sec. School, Sirsa

Date: 01-01-2024

M.S. Grills haven been provided to up windows

R.C.C. slabs with intermediate R.C.C. beams have been provided, covered with tile terracing and partially with cement toping in some portion.

Kota Stone has been provided in left wing of the building while C V. Mooring has been provided in rest of the building ceramic tile flooring also been provided in some portion of the building.

No cracks at any point has been

No such defects have been found in the building.

The Building has been well maintained

The Structure is sound safe and is fit for conducting the classes

The Building is located in plane area in northern indian in safe zone. The site doesn't fall in flood prone area & no abnormal wind pressure with high intensity has been eperienced causing damage to the structure.

No other observation leading to any doubt about safety of structure



/vekanand(B.M) Sr. Sec. School SIRSA((**rvana)